



# IECEX Quality Assessment Report Summary

## INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit [www.iecex.com](http://www.iecex.com)

QAR Ref. No.: **NO/NEM/QAR08.0008/11** Page 1 of 2  
QAR Free Ref. No.: **NEM-QAR-433202** Status: **Issued**  
Details of change: Re-assessment audit Date of issue: **2021-11-01**  
Site(s) audited: **PMV Automation AB** Valid until: **2024-08-11**  
Korta Gatan 9  
SE-171 54 Solna  
SWEDEN  
**Sweden** Audit date: **2021-08-11**

**Brovex Mekaniska Verkstad AB**  
Garpenbergsgatan 4  
Spånga SE-16353  
**Sweden**

**Väsby Finmekanik AB**  
Mellangården 6  
Uppland Väsby SE-19451  
**Sweden**

**Flowserve Corporation**  
14219 Westfair West Drive  
Houston TX 77041  
**United States of America**

**ProvideU Assembly OÜ**  
Laki 12  
Tallinn 10 621  
**Estonia**

**Flowserve US, Inc., Cookville Operation**  
1978 Foreman dr.  
Cookville TN 38501  
**United States of America**

**Unimet d.o.o.**  
Delfe Ivanic 51  
21241 Kac  
**Serbia**

Issuing ExCB: **NEM - DNV Product Assurance AS**

Manufacturer: **PMV Automation AB**  
Korta Gatan 9  
SE-171 54 Solna  
SWEDEN

Location of  
Manufacturer: **Sweden**

Product information: Valve control systems; Feedback units; I/P Converters; Switchboxes; Positioners

Protection concept: **Ex ia, Ex d, Ex e, Ex mb, Ex tD, Ex tb, Ex h**

Related QARs:

[NO/NEM/QAR08.0008/00](#)  
[NO/NEM/QAR08.0008/03](#)  
[NO/NEM/QAR08.0008/06](#)  
[NO/NEM/QAR08.0008/09](#)

[NO/NEM/QAR08.0008/01](#)  
[NO/NEM/QAR08.0008/04](#)  
[NO/NEM/QAR08.0008/07](#)  
[NO/NEM/QAR08.0008/10](#)

[NO/NEM/QAR08.0008/02](#)  
[NO/NEM/QAR08.0008/05](#)  
[NO/NEM/QAR08.0008/08](#)



# IECEX Quality Assessment Report Summary

QAR Ref. No.: **NO/NEM/QAR08.0008/11**

Page 2 of 2

Related Certificates (manual insertion)::

Related Certificates (automatic linking)::

Related Certificates for  
previous versions:

IECEX NEM 09.0001 issue: 0  
IECEX NEM 09.0007X issue: 0  
IECEX NEM 09.0022 issue: 0  
IECEX NEM 11.0012X issue: 2  
IECEX NEM 13.0008X issue: 2  
IECEX PRE 17.0072X issue: 0  
IECEX SIR 06.0007X issue: 3  
IECEX SIR 06.0007X issue: 6

IECEX NEM 09.0001 issue: 1  
IECEX NEM 09.0007X issue: 1  
IECEX NEM 11.0012X issue: 0  
IECEX NEM 13.0008X issue: 0  
IECEX PRE 17.0046X issue: 0  
IECEX PRE 18.0076X issue: 0  
IECEX SIR 06.0007X issue: 4  
IECEX SIR 20.0030X issue: 0

IECEX NEM 09.0001 issue: 2  
IECEX NEM 09.0007X issue: 2  
IECEX NEM 11.0012X issue: 1  
IECEX NEM 13.0008X issue: 1  
IECEX PRE 17.0046X issue: 1  
IECEX PRE 20.0112X issue: 0  
IECEX SIR 06.0007X issue: 5

Comments: Reassessment audit conducted 2021-05-19 to 21, 2021-05-26 to 28, covering the resp. manufacturer, the factories in Sweden, the factory in Serbia and the factory in Estonia. The factory in Cookeville, TN and Houston, TX, USA were covered in a separate audits 2021-06-02 to 03, reports ref. 433203.  
Next surveillance audit planned to 2022-11.