



IECEX Quality Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

QAR Ref. No.: **NO/PRE/QAR16.0042/03** Page 1 of 2
QAR Free Ref. No.: **NEM-QAR-433203** Status: **Issued**
Details of change: Re-assessment audit Date of issue: **2021-11-04**
Site(s) audited: **Flowserve Corporation** Valid until: **2024-08-11**
14219 Westfair West Drive Audit date: **2021-08-11**
Houston TX 77041
United States of America

Palmstierna International AB
Korta Gatan 9
SE-171 54 Solna
Sweden
Sweden

Brovex Mekaniska Verkstad AB
Garpenbergsgatan 4
Spånga SE-16353
Sweden

Flowserve US, Inc., Cookville Operation
1978 Foreman dr.
Cookville TN 38501
United States of America

Unimet d.o.o
Delfe Ivanic 51
Kac 21241
Serbia

ProvideU Assembly OÜ
Laki 12
Tallinn 10 621
Estonia

Väsby Finmekanik AB
Mellangården 6
Uppland Väsby SE-19451
Sweden

Issuing ExCB: **PRE - DNV Product Assurance AS**

Manufacturer: **Palmstierna International AB**
Korta Gatan 9
SE-171 54 Solna
SWEDEN

Location of
Manufacturer: **Sweden**

Product information: Valve Control Systems; Feedback Units; I/P Converters; Switchboxes; Positioners

Protection concept: **Ex ia, Ex d, Ex e, Ex mb, Ex tD, Ex tb, Ex h**

Related QARs:

[NO/PRE/QAR16.0042/00](#)

[NO/PRE/QAR16.0042/01](#)

[NO/PRE/QAR16.0042/02](#)

Related Certificates (manual insertion)::



IECEX Quality Assessment Report Summary

QAR Ref. No.: **NO/PRE/QAR16.0042/03**

Page 2 of 2

Related Certificates (automatic linking)::

Related Certificates for
previous versions:

Comments:

Reassessment audit conducted 2021-05-19 to 21, 2021-05-26 to 28, covering the resp. manufacturer, the factories in Sweden, the factory in Serbia and the factory in Estonia. The factory in Cookeville, TN and Houston, TX, USA were covered in a separate audits 2021-06-02 to 03, reports ref. 433203. Next surveillance audit planned to 2022-11.